

**To:** Salazar, Matt[Salazar.Matt@epa.gov]  
**From:** McKaughan, Colleen  
**Sent:** Thur 5/7/2015 4:53:41 PM  
**Subject:** FW: Fwd: record request/Hickman's Arlington facility  
[image001.png](#)  
[image005.jpg](#)  
[cc259144.pdf](#)  
[cc259144 additional info.doc](#)

Hi, Matt,

Do you want to look at this information and give Maricopa County a call to see what's going on?

## Ex. 5 & 7

Colleen

**From:** Don't Waste Arizona [mailto:dwaz@fastq.com]  
**Sent:** Thursday, May 07, 2015 9:27 AM  
**To:** McKaughan, Colleen  
**Subject:** Fw: Fwd: record request/Hickman's Arlington facility

From what I can gather, the rotary kiln is emitting thick black smoke, and nothing is being done to stop it or regulate it.

Best,

Steve Brittle

DWAZ

**From:** [Dan](#)

**Sent:** Wednesday, May 06, 2015 11:53 AM

**To:** [Hether Krause - ENVX](#)

**Cc:** [Daniel Blackson](#)

**Subject:** Fwd: record request

Ms. Krause,

I guess this is related to the complaint that you filed. As normal, nothing is being done and no observation is not performed when the machine is started up. However, the observation does seem to verify that the opacity limit is violated.

Please note that this does not resolve my concern that a Non-Title V Air Quality Air Permit is required to operate this equipment. What is the status of this regulatory requirement?

Dan

Sent from my iPad

Begin forwarded message:

**From:** Rachel Danley - AQDX <[RachelDanley@mail.maricopa.gov](mailto:RachelDanley@mail.maricopa.gov)>

**Date:** May 5, 2015 at 4:50:45 PM MST

**To:** "[blackson.daniel@yahoo.com](mailto:blackson.daniel@yahoo.com)" <[blackson.daniel@yahoo.com](mailto:blackson.daniel@yahoo.com)>

**Subject:** record request

Good Afternoon,

Complaint report cc259144 is attached.

Thank you,

**Rachel Danley**

**Administrative Operations Specialist**

Maricopa County Air Quality Department

1001 North Central Avenue, Suite 125

Phoenix, Arizona 85004

*Located at the Central Ave. & Roosevelt METRO stop*

602-506-6201

[CleanAirMakeMore.com](http://CleanAirMakeMore.com)

---

---

---

---

---

---

---

---

---

---

Ms. Krause,

I guess this is related to the complaint that you filed. As normal, nothing is being done and no observation is not performed when the machine is started up. However, the observation does seem to verify that the opacity limit is violated.

Please note that this does not resolve my concern that a Non-Title V Air Quality Air Permit is required to operate this equipment. What is the status of this regulatory requirement?

Dan

Sent from my iPad

Begin forwarded message:

> From: Rachel Danley - AQDX <[RachelDanley@mail.maricopa.gov](mailto:RachelDanley@mail.maricopa.gov)>  
> Date: May 5, 2015 at 4:50:45 PM MST  
> To: "[blackson.daniel@yahoo.com](mailto:blackson.daniel@yahoo.com)" <[blackson.daniel@yahoo.com](mailto:blackson.daniel@yahoo.com)>  
> Subject: record request  
>  
> Good Afternoon,  
>  
> Complaint report cc259144 is attached.  
>  
> Thank you,  
>  
> Rachel Danley  
> Administrative Operations Specialist  
> Maricopa County Air Quality Department  
> 1001 North Central Avenue, Suite 125  
> Phoenix, Arizona 85004  
> Located at the Central Ave. & Roosevelt METRO stop  
> 602-506-6201  
> [CleanAirMakeMore.com](http://CleanAirMakeMore.com)  
>  
>  
>

-----

No virus found in this message.

Checked by AVG - [www.avg.com](http://www.avg.com)

Version: 2015.0.5863 / Virus Database: 4342/9718 - Release Date: 05/07/15